

Ver17-SP1.1 SheetWorks for Unfold (Addin) 64bit Patch Version Installation Procedure
Amada CO., LTD.

***** Improvements *****

[Analyze Shapes]

- afpc4056/afpc4142

Fixed an issue of forming shape recognition process.

[Create Sheet Metal Solid]

- Fixed an issue that failed to cancel highlighted display while selecting [Part Name] if the option [Multi Parts] which makes all the parts highlighted is selected.

- afpc4212

Fixed an issue that mistakenly deselected all the settings if the option [Multi Parts] is selected while [Faces to Remove] is also selected.

[Create Unfold Drawing]

- afpc1839/afpc3070

Fixed an issue of the neutral face creating process for curved faces that failed to create flat parts.

- afpc3768

Fixed an issue of Bend Relief Arc creating process that failed create correct shapes.

- afpc3970

Fixed an issue of unfolding target face searching process that failed to create correct flat parts.

[Auto Dimension]

- afpc4163

Fixed an issue of minute cylinder face recognition process that failed to create correct dimensions.

[Save AP and Estimation Data]

- afpc3754

Fixed a crash due to minute arcs.

[Load from SDD]

- afpc4236

Fixed a crash due to overlapping outer lines during the flange creating process.

[Analyze Tube Shapes]

- afpc3548

Fixed an issue of front/back face recognition process.

[Create Tube Unfold]

- afpc2377/afpc4121

Fixed an issue of the process to convert curved lines to arcs that made many minute entities.

[Send to Dr.ABE_Tube]

- afpc4042

Fixed an issue of the process to recognize projection holes on flat parts that failed to output some projection holes correctly.

[Positioning Tab]

- afpc4261

Improved the warning message that appears if adjacent faces of a selected edge are not perpendicular.

***** Installation Precautions *****

- (1) Close SolidWorks before starting installation.
- (2) This patch file is effective for the target software and version only.
Confirm that the target software and version is installed.
- (3) The target software is SheetWorks for Unfold (Addin).
- (4) This patch is NOT effective for SheetWorks for Unfold (Embedded), SheetWorks for Design,
and SheetWorks for Tube.
- (5) The target software version is [Ver17-SP1.0 (17.1.0.1)].
- (6) The version number will be [17.1.1.1] after installation.

***** Installation Procedure *****

- (1) Close SolidWorks in the installation destination machine.
 - (2) Run [V17SP1.1Patch_Unfold_Addin_64.exe].
 - (3) Proceed installation according to the dialog.
- @* If the [Program Compatibility Assistant] window appears while installing, select either [This program installed correctly] or [Cancel].